

Delta Secondary School Boiler Room Floor Repairs



Project: Delta Secondary School
Boiler Room Floor Repairs

Location: Hamilton, ON

Client: Hamilton Wentworth District School
Board

Completion: September, 2006

Background:

Built in the early 1900's, Delta Secondary School is Hamilton's oldest high school. Building maintenance personnel at the school were experiencing some problems in the boiler room. Water was leaking from the boilers into cracks and joints in the concrete floor and making it's way into the boys' gymnasium through the shared wall. This opened up the opportunity for further damage in the gymnasium and posed a potential safety hazard to students.



Scope of Work:

Advanced Concrete Solutions was called upon to provide a solution. The proposed scope of work included the following:

- preparation and installation of a 4" high seamless epoxy cove to all perimeter wall/floor joints - approximately 350 lin. ft.
- preparation of over 275 lin.ft. of floor cracks and application of a high performance polyurethane sealant.



Having completed hundreds of similar projects in the past, ACS technicians had the expertise and experience required to recommend the appropriate solution and to execute the work safely and effectively.

Advanced Concrete Solutions

88 Fraser Street, Caledonia, ON N3W 1J9

Cell: (905) 379-7156

Fax: (905) 765-0505

advancedconcretesolutions@sympatico.ca



ADVANCED CONCRETE
S O L U T I O N S